

Form 9-381a
(March 1942)

Budget Bureau No. 42-R358.
Approval expires 11-30-46.

APPROVED
NOV 25 1949
P. J. M. *[Signature]*
REGISTERED ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 078009

Unit Oil

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 20, 1949, 19

Well No. 1 is located 990 ft. from N line and 990 ft. from E line of sec. 8.

NE 1/4 NE 1/4 27N 13W 100° 00'
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5938 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Report on Douthit well.

We obtained the ten-inch casing and ran 2222' of it in the hole.
The total depth of the hole is now 2295', and we are underreaming in an effort to get the pipe down below the water sand and get a water shut-off.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company P. E. English

Address Box 577
Farmington, New Mexico

By Leroy English
Engineer San Juan
Title San Juan