

APPROVED NOV 14 1949
P. J. M. [Signature]
DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 070009
Unit _____

RECEIVED

NOV 8 1949

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 5, 1949

Well No. 1 is located 990 ft. from N line and 990 ft. from E line of sec. 8

(1/4 Sec. and 1/4 Sec. No.) 100.1 (Twp.) 23 (Range) 15 (Meridian) 7
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5932 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Weekly Report on Southit well No. 1
No change. Still waiting on 10" casing which is ordered, but not delivered.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company P. R. English
Address Box 572
Emmerton, N.H.
By [Signature]
Title Engineer