

NEW MEXICO OIL CONSERVATION COMMISSION  
Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL	X	REPORT ON RECOMPLETION OPERATION		REPORT ON (Other)	

September 23, 1953

Farmington, New Mexico

(Date)

(Place)

Following is a report on the work done and the results obtained under the heading noted above at the

BENSON-MONTIN

GALLEGO CANYON UNIT

(Company or Operator)

(Lease)

BENSON-MONTIN

Well No. 29 in the SE 1/4 SW 1/4 of Sec. 32

(Contractor)

T. 29N, R. 12W, NMPM., WEST KUTZ Pool, SAN JUAN County.

The Dates of this work were as follows: 9-18-53 to 9-22-53

Notice of intention to do the work (was) (was not) submitted on Form C-102 on \_\_\_\_\_, 19\_\_\_\_\_,  
(Cross out incorrect words)  
and approval of the proposed plan (was) (was not) obtained.

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Drilled to TD 1540'. Well making approximately 6 gallons of salt water per hour. Gas too small to measure - estimated at 1 MCF per day.

Plugged back with cement from TD 1540' to 1420' (30' in casing). Shot 7" casing at 546' and pulled 17 joints. Dumped 15 sacks cement at 400'. Spotted cement plugs in top and bottom of 10-3/4" surface casing. Erected marker.

Well plugged and abandoned.

Witnessed by \_\_\_\_\_  
(Name) (Company) (Title)

Approved: OIL CONSERVATION COMMISSION

\_\_\_\_\_  
(Name)

Oil and Gas Inspector Dist. #3.

(Title)

10-2-53  
\_\_\_\_\_  
(Date)

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name: Robert C. Green  
Position: Field Superintendent

Representing: Benson-Montin

Address: 3151 West Main, Farmington, New Mexico

U.S. CONSERVATION COMMISSION	
AZTEC DISTRICT OFFICE	
No. Copies Received	2
Date	12/1/71
County	1
State	1
Project Number	
Project Name	
U.S. Office	
Transmittal	
File	