


Bloomfield Oil and Gas Co. W.D. Abrams #5-

This photograph was taken by Mr. Charles Bohlen on April 11, 1978. The casing is leaking at the surface causing the scale deposition on the wellhead and puddle of sulfur water both seen in the photo.

1. Source of pollution at surface
2. Threat of pollution to other underground strata
3. Within 100 yards of residences



E 30-045-08064
STATE NEW MEXICO
COUNTY San Juan SEC. 23 T. 29N R. 11W
FIELD OR AREA Bloomfield (Katz-Fulcher) LOCATION 300' W, 1620' N
LEASE Abrams, H. D. WELL NO. 5
COMPANY Bloomfield Oil & Gas SPD. _____ COMPLETED _____
ELEV. 5470' T.D. 740' P.B. 670'
CASING 10" @ 55' set 6-5/8" @ 647' set

SHOT OR ACID _____

PERF. _____

I.P. 2,000,000 cu. ft. gas

PRODUCING FORM _____

PRODUCTIVE DEPTH OR INTERVAL _____

REMARKS:

Abandoned