

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Local Office **Santa Fe**
Lesse No. **068990**
Unit **J. J. Hudson #1**

Approved
10-3
P. J. M.

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 14, 1953 19

Well No. **1 Hudson** is located **1650** ft. from **N** line and **2310** ft. from **W** line of sec. **34**
SE 1/4 NW 1/4, Section 34 **T-30-N, R-13-E** **N.M.P.M.**
 (1/4 Sec. and Sec. No.) (Twp) (Range) (Meridian)
Pulcher Basin **San Juan County** **New Mexico**
 (Field) (County or Sub-division) (State or Territory)

The elevation of the derrick floor above sea level is **5739** ft. **17**

DETAILS OF WORK

(State means of and expected depths to objective sands; show logs, weights, and lengths of pipe, and all other important proper)


ILLEGIBLE

5 1/2" Casing shot loose at 1100 feet - 1100 feet of 5 1/2"
 1 1/2" Casing pulled - 25 sacks cement plug set in stub of pipe
 at 1100 feet. 10 sacks cement plug set in surface casing.
 Marker erected and location cleaned.

I understand that this plan of work must receive approval in writing by the Geological Survey.

Company **ATTEC OIL & GAS COMPANY**
 Address **P O Box 815**
Perwington, New Mexico

By **H. C. Montgomery**
 Title **Drilling Superintendent**



1

1. The first step in the process of identifying a problem is to recognize that a problem exists. This involves gathering information about the situation and identifying the specific issue that needs to be addressed.

1. *Chlorophyll a* and *Chlorophyll b* were determined by the method of Arar and Collins (1971).

1. *Phragmites australis* (Cav.) Trin. ex Steud. (Common reed)