

U.S. LAND OFFICE
RECEIVED
LEASE OF PERMIT TO PROSPECT

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

TOP OF OIL OR GAS WELL

LOCATE WITH CONFIDENCE

10-sack cement plug in top of 8-5/8" surface casing, which was left in the hole, and the hole was abandoned. The information given by the well log and the well log was determined from all available records.

[illegible]

to sulfate.
IMPROVED WATER BAKED
No. 8-10-26-56 Moved in rotary. Pressured up on 8-5/8" casing to 500#. No pressure decrease in 30 minutes.
No. 10-2-56 TD 1741'. Gas Schlumberger. Spotted cement plugs as follows:
(See page 2)

10-13-56 Moved in snothole rig to set surface casing. Spudded.

It is of the greatest importance to have a complete history of the well. Please state in detail the dates of redrilling, together with the reasons for the work and its results. If there were any changes made in the casing, state fully, and if any casing was "sidetracked", or left in the well, give its size and location. If the well has been dynamited, give date, size, position, and number of shots. If plugs or bridges were put in to test for water, state kind of material used, position, and results of pumping or bailing.

HISTORY OF OIL OR GAS WELL

16-43094-2 U. S. GOVERNMENT PRINTING OFFICE

[illegible]