OIL CONSERVATION COMMISSION

SANTA FE, NEW MEXICO

Miscellaneous Reports on Wells

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

The dates of this work were as follows: September 25,1950 too September 29,1 Notice of intention to do the work was (was MMX submitted on Form C-102 on September 20, and approval of the proposed plan was (was nMX obtained (Cross out incorrect words.) DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED The number 1 Israel was deepend by Denmam Drilling Co. as co Mountain Oil And Gas Co. was carried to a total depth of 171 top of the Picture Cliff sand, and 1710 feet of 6 5/8 inch ca cemented with 50 sacks of cement. The picture cliff sand wil with cable tools as soon as the company spudder is repaired.	SE
CHEMICAL TREATMENT OF WELL REPORT ON RESULT OF TEST OF CASING REPORT ON RESULT OF PLUGGING OF WELL October 3. 1950 Date Parmington Ne October 3. 1950 Date Farmington Ne Oli, Conservation commission, Santa FE, New Mexico. Gentlemen: Following is a report on the work done and the results obtained under the heading noted above at the Mountain Oil And Gas Company Company or Operator Company or Operator Jesse J. SN 1/2 SE 1/2 NE 1/2 Of Sec. 14 To San Juan The dates of this work were as follows: September 25, 1950 too September 29, 1 Notice of intention to do the work was (was MEX obtained (Cross out incorrect words.) DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED The number 1 Israel was deepend by Denman Drilling Co. as co Mountain Oil And Gas Co. was carried to a total depth of 171 top of the Picture Cliff sand, and 1710 feet of 6 5/8 inch ca cemented with 50 sacks of cement. The picture cliff sand with with cable tools as soon as the company spudder is repaired.	SE
October 3. 1950 Farmington Ne October 3. 1950 Farmington Ne OL CONSERVATION COMMISSION, SANTA FE, NEW MEXICO. Gentlemen: Following is a report on the work done and the results obtained under the heading noted above at the Mountain Oil And Gas Company Israel well No. NO. C.SN 18E 1NE 1 Well No. NO. Lease C.SN 18E 1NE 1 Of Sec. 14 TON R. 12W Mildcat Field San Juan The dates of this work were as follows: September 25,1950 too September 29,1 Notice of intention to do the work was (was NEW submitted on Form C-102 on September 20, and approval of the proposed plan was (was NEW submitted on Form C-102 on September 20, and approval of the proposed plan was (was new obtained (Cross out incorrect words.) DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED The number 1 Israel was deepend by Denmam Drilling Co. as common the Picture Cliff sand, and 1710 feet of 6 5/8 inch can be companied with 50 sacks of cement. The picture cliff sand will with cable tools as soon as the company spudder is repaired.	
October 3. 1950 Farmington New Mexico. Gentlemen: Following is a report on the work done and the results obtained under the heading noted above at the Mountain Oil And Gas Company Israel Well No. No. Company or Operator C.SN 18E 1NE 1 Of Sec. 14 TON RESULTS OF SEC. 15 TON RESULTS OF SEC. 16 TON RESULTS OF SEC. 17 TON TON RESULTS OF SEC. 17 TON	X
Conservation commission, Santa FE, NEW MEXICO. Sentlemen: Following is a report on the work done and the results obtained under the heading noted above at the Mountain Oil And Gas Company Israel well No. NO. Lease C. SN 1 SE 1 NE 1 Of Sec. 14 TON R 12W Laildcat Field San Juan The dates of this work were as follows: September 25, 1950 too September 29, 1 Notice of intention to do the work was (was MEX obtained (Cross out incorrect words.) DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED The number 1 Israel was deepend by Denmam Drilling Co. as confountain Oil And Gas Co. was carried to a total depth of 171 top of the Picture Cliff sand, and 1710 feet of 6 5/8 inch can be comented with 50 sacks of cement. The picture cliff sand will with cable tools as soon as the company spudder is repaired.	-
OIL CONSERVATION COMMISSION, SANTA FE, NEW MEXICO. Gentlemen: Following is a report on the work done and the results obtained under the heading noted above at the Mountain Oil And Gas Company Israel well No. NO. Company or Operator Lease C. SW 1 SE 1 NE 1 Of Sec. 14 TON R 12W C. SW 2 SE 1 NE 1 OF Sec. 14 TON R 12W C. SW 2 SE 1 NE 1 OF Sec. 14 TON R 12W C. SW 2 SE 1 NE 1 OF Sec. 14 TON R 12W C. SW 3 SE 1 NE 1 OF Sec. 14 TON R 12W C. SW 2 SE 1 NE 1 OF Sec. 14 TON R 12W C. SW 2 SE 1 NE 1 OF Sec. 14 TON R 12W C. SW 2 SE 1 NE 1 OF Sec. 14 TON R 12W C. SW 3 SE 1 NE 1 OF Sec. 14 TON R 12W C. SW 4 SE 1 NE 1 OF Sec. 14 TON R 12W C. SW 2 SE 1 NE 1 OF Sec. 14 TON R 12W C. SW 2 SE 1 NE 1 OF Sec. 14 TON R 12W C. SW 3 SE 1 NE 1 OF Sec. 14 TON R 12W C. SW 4 SE 2 NE 1 OF Sec. 14 TON R 12W C. SW 4 SE 2 NE 1 OF Sec. 14 TON R 12W C. SW 4 SE 2 NE 1 OF Sec. 14 TON R 12W C. SW 4 SE 2 NE 1 OF Sec. 14 TON R 12W C. SW 4 SE 2 NE 1 OF Sec. 14 TON R 12W C. SW 4 SE 2 NE 1 OF Sec. 14 TON R 12W C. SW 4 SE 2 NE 1 OF Sec. 14 TON R 12W C. SW 4 SE 2 NE 1 OF Sec. 14 TON R 12W C. SW 4 SE 2 NE 1 OF Sec. 14 TON R 12W C. SW 4 SE 2 NE 1 OF Sec. 14 TON R 12W C. SW 4 SE 2 NE 1 OF Sec. 14 TON R 12W C. SW 4 SE 2 NE 1 OF Sec. 14 TON R 12W C. SW 4 SE 2 NE 1 OF Sec. 14 TON R 12W C. SW 4 SE 2 NE 1 OF Sec. 14 TON R 12W C. SW 4 SE 2 NE 1 OF Sec. 14 TON R 12W C. SW 4 SE 2 NE 1 OF SEC. 14 TON R 12W C. SW 4 SE 2 NE 1 OF SEC. 14 TON R 12W C. SW 4 SE 2 NE 1 OF SEC. 14 TON R 12W C. SW 4 SE 2 NE 1 OF SEC. 14 TON R 12W C. SW 4 SE 2 NE 1 OF SEC. 14 TON R 12W C. SW 4 SEC. 14 TON R 12W	Mexico
Mountain Oil And Gas Company Israel well No. NO. Company or Operator Lease 12W 12W Lease 12W Lease 12W Lease 12W 12W Lease 12W 12W Lease 12W 12W Lease 12W Lease 12W Lease 12W 12W Lease 12W 12W Lease 12W Lease 12W 12W Lease 12W 12W Lease 12W 12W Lease 12W 12W 12W Lease 12W 12W 12W Lease 12W 12W Lease 12W 12W 12W Lease 12W 12W 12W 12W 12W 12W 12W 12	lace
Company or Operator C. SW 1 SE 1 NE 1 of Sec. 14 TON RELEASE Mildcat Field San Juan The dates of this work were as follows: September 25,1950 too September 29,1 Notice of intention to do the work was (was proximated on Form C-102 on September 20, and approval of the proposed plan was (was not obtained (Cross out incorrect words.) DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED The number 1 Israel was deepend by Denmam Drilling Co. as common and the proposed plan was carried to a total depth of 171 top of the Picture Cliff sand, and 1710 feet of 6 5/8 inch can common the proposed with 50 sacks of cement. The picture cliff sand will with cable tools as soon as the company spudder is repaired.	
C.SW 1SE NE NE NE Of Sec. 14 TON R 12W Wildcat Field San Juan The dates of this work were as follows: September 25,1950 too September 29,1 Notice of intention to do the work was (was MAX obtained (Cross out incorrect words.) DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED The number 1 Israel was deepend by Denmam Drilling Co. as co Mountain Oil And Gas Co. was carried to a total depth of 171 top of the Picture Cliff sand, and 1710 feet of 6 5/8 inch ca cemented with 50 sacks of cement. The picture cliff sand will with cable tools as soon as the company spudder is repaired.	
The dates of this work were as follows: September 25,1950 too September 29,1 Notice of intention to do the work was (was proximitted on Form C-102 on September 20, and approval of the proposed plan was (was not obtained (Cross out incorrect words.) DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED The number 1 Israel was deepend by Denmam Drilling Co. as common that in Oil And Gas Co. was carried to a total depth of 171 top of the Picture Cliff sand, and 1710 feet of 6 5/8 inch can cemented with 50 sacks of cement. The picture cliff sand will with cable tools as soon as the company spudder is repaired.	, N. M. P. M
The dates of this work were as follows: September 25,1950 too September 29,1 Notice of intention to do the work was (was MMX obtained on Form C-102 on September 20, and approval of the proposed plan was (was nMX obtained (Cross out incorrect words.) DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED The number 1 Israel was deepend by Denmam Drilling Co. as co Mountain Oil And Gas Co. was carried to a total depth of 171 top of the Picture Cliff sand, and 1710 feet of 6 5/8 inch ca cemented with 50 sacks of cement. The picture cliff sand will with cable tools as soon as the company spudder is repaired.	
Notice of intention to do the work was (was proximitted on Form C-102 on September 20, and approval of the proposed plan was (was not obtained (Cross out incorrect words.) DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED The number I Israel was deepend by Denmam Drilling Co. as common that the picture Cliff sand, and 1710 feet of 6 5/8 inch can common the picture Cliff sand, and 1710 feet of 6 5/8 inch can common that the picture cliff sand will with cable tools as soon as the company spudder is repaired.	50
DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED The number 1 Israel was deepend by Denmam Drilling Co. as co Mountain Oil And Gas Co. was carried to a total depth of 171 top of the Picture Cliff sand, and 1710 feet of 6 5/8 inch ca cemented with 50 sacks of cement. The picture cliff sand will with cable tools as soon as the company spudder is repaired.	
The number I Israel was deepend by Denmam Drilling Co. as co Mountain Oil And Gas Co. was carried to a total depth of 171 top of the Picture Cliff sand, and 1710 feet of 6 5/8 inch ca cemented with 50 sacks of cement. The picture cliff sand will with cable tools as soon as the company spudder is repaired.	
Mountain Oil And Gas Co. was carried to a total depth of 171 top of the Picture Cliff sand, and 1710 feet of 6 5/8 inch ca cemented with 50 sacks of cement. The picture cliff sand wil with cable tools as soon as the company spudder is repaired.	
	ing lande
Subscribed and sworn before me this	Inspector
der of October 19 50. Name Carry	tion given aboy
Hult Emit Position President	tion given aboy
Notary Public Representing MOUNTain Oil & Company or Operato	tion given aboy
My commission expires 6-1-51 Address Box 1202 Hobbs, N	tion given abov
	Gas Co.