(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	;	3	9	ņ	t	a	 Fe	

Lease No. 078198

Unit _____ 3/2_ Sec. 1 Nye 3

OIT COR COM

SUNDRY NOTICES AND REPORTS ON WELLS NOTICE OF INTENTION TO DRILL NOTICE OF INTENTION TO CHANGE PLANS NOTICE OF INTENTION TO TEST WATER SHUT-OFF NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL NOTICE OF INTENTION TO SHOOT OR ACIDIZE NOTICE OF INTENTION TO PULL OR ALTER CASING NOTICE OF INTENTION TO PULL OR ALTER CASING NOTICE OF INTENTION TO ABANDON WELL NOTICE OF INTENTION TO ABANDON WELL SUBSEQUENT REPORT OF REDRILLING OR REPAIR SUBSEQUENT REPORT OF ABANDONMENT SUBSEQUENT REPORT OF ABANDONMENT

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

		ly 17,
Well No. 3 Nya is located 1650 for	t. from $\frac{\mathbf{x} \mathbf{b} \mathbf{i} \mathbf{k}}{ \mathbf{S} }$ line and 990 ft	from line of sec. 1
SW/4 Sec. 1 30 No.		· ·
Semi_Wildoat San J	(New Mexico (State or Territory)
The elevation of the derrick floor above se	a level is 5909 ft.	(Sand a Territory)
	TAILS OF WORK	
(State names of and expected depths to objective sands; she ing points, and	ow sizes, weights, and lengths of proposed d all other important proposed work)	casings; indicate mudding jobs, coment 51
***		OIL COM. COM. DIST. 3
Well was shot from 47	27 to 5030 with 7	65 qts. nitr

glycerin. Well tested 84 MCF before shot, and 1118 MCF 6 hours after shot. Cleaning out.

I understand that this plan of work must receive approval in writing by the	e Geological Survey before operations may be commanded
Company SOUTHERN UNION GAS COMPANY	
Address 1104 Burt Bldg.	
Dallas, Texas	By HC Markenery (4)
	Title Drilling Superintendent