(SUBMIT IN TRIPLICATE)

UNITED STATES

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	asvaje	incir.
	1-140-1	

uit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF.	3
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

		Aaren 18	, 19
Well No. is locat	ed 1980 ft. from S line ar	ad from $\left\{\begin{array}{c} E \\ \bullet \end{array}\right\}$ line of	sec34
821/4 of Sal/4 sec.	34 -31-4 17-4	M MIM	
(1/4 Sec. and Sec. No.)	(Twp.) (Range)	(Meridian)	
*ildcst	Saa Jusa	New Paxled)
(Field)	(County or Subdivision)	(State or Territory)	

The elevation of the derrick floor above sea level is 5226 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total Depth 4417' Shale.

Set and comented 4399' of 9-5/6", 36y and 40g, J-55, Seculoss Casing at 4410' with 250 sacks. Completed comenting at 5:00 A.M. 3-12-5%. Top of coment behind casing 3600', by temperature survey.

before and after drilling plug with 550% pressure. Tested to K., no pressure drop in 15 minutes.

I understand	d that this plan of work must receive approval in writ	ing by the Geological Survey before operations may be commenced.
Company	The Texas Contany	
Address	7 sox 1271	
	了在指字台。	By Brommon &
~**************************************		Title Assist. Bist. Apt.