(SUBMIT IN TRIPLICATE)

UNITED STATES

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Maya jo	Iribal
Lease No	[-149-]	KD-7653

SUNDRY NOTICES AND REPORTS ON WELLS

OTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
IOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		Subsequent Report of Si	- - #-

	A	April 22	
Well Nois locat	ed 1966 t. from S line and	660 ft. from $\{E\}$ line of $\{E\}$	sec 34
18 of 32 Sec. 34 (9 Sec. and Sec. No.)	31-N 17-W (Range)	(Meridian)	
hildent	San Juan	Sew Kexico	
(Field)	(County or Subdivision)	(State or Territory)	

The elevation of the derrick floor above sea level is 3.5226 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, comenting points, and all other important proposed work)

Total Depth 6896' Lime. On 4-20-52 took 507 77 from 6876' to 6898'. Tool open 2 ars. Steady but week blow of sir thrubut test. Accovered 60 feet drilling mad. Steady and 15 minute shut in 887-09. Hydrostatic Pressure 33809.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.			
Company	The Tuxas Company		
Address	P. C. Box 1281		
	AMA TOXAR	By Phrommon 3	
		Title Sast. Sist. Supt.	