

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency **The Ute Mountain**
Tribe of **the Ute Mountain Reservation**

Allottee
Contract No. **14-20-604-1944**
Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 4, 1958, 19 58

Well No. **Ute 31-1** is located **990** ft. from **N** line and **910** ft. from **W** line of sec. **31**

SW/4 Sec. 31 **T32N** **R 15 W**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat **San Juan** **New Mexico**
(Field) (County or Subdivision) (State or Territory)


The elevation of the derrick floor above sea level is **6631** ft. **OK**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

July 21, 1958 Surface pipe was set on the above described well. The pipe consisted of 9 jts. 349.62 ft. 13 3/8" O.D. 40# E-40 new J & L casing. It was set at 364 ft. K.B. and cemented with 330 sacks, regular. Cement was circulated. The pipe was tested with 750 psi for 2 hrs. it held OK.

ILLEGIBLE



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Forest Oil Corporation**

Address **1610 Denver Club Building**

Denver, Colorado

By **C. W. Hansen**
Title **Production Superintendent**