

1-28-85

30-045-26209

N

NSL-1865

F. Loc. 980/S; 1265/E Elev. 5540 GL Spd. Cu. ft. TD Cu. ft. PB
Casing S. @ W' S' Int. @ W' S' Pr. @ W' S' I. @ T Gas
Cug. Perf. Prod. Slim.

BO/D MCF/D After Hrs. SICP PSI After Days GOR Grav. 1st Del. Gas
1st Del. Oil

TOPS		NITD	X	Well Log	TEST DATA						Ref. No.
Op Alamo		C-103		Plat X	Schd.	PC	Q	PW	PD	D	
Kirtland		C-104		Electric Log							
Fruitland				C-122							
Pictured Cliffs		Ditr		Dfo							
Chacra		Dair		Doc							
Cliff House		APD EXAMINER 7-24-86									
Menefee											
Point Lookout											
Mancos											
Gallup											
Greenhorn											
Dakota											
Entrada											
NSL-1865 Acres S/320											

P
Basin Dak. Co. SJ S 16 T 28N R 12W U P Oper. Amoco Production Co. LeGallegos Canyon U. No. 215E

Gallegos Canyon Unit #215E

P-16-28N-12W

AMOCO PRODUCTION CO.

Caller Service 4104
Farmington, New Mexico 87499

SEP 04 1986

CERTIFIED--RETURN RECEIPT REQUESTED

Amoco Production Company
2325 East 30th Street
Farmington, NM 87401

Gentlemen:

Enclosed is your Application for Permit to Drill (APD) well No. 215 E GCU, SE/4SE/4 sec. 16, T. 28 N., R. 12 W., San Juan County, New Mexico, lease I-149-IND-8475. The subject APD is rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 15 days, we will presume that no construction occurred. Later discovery that construction activities have in fact occurred, will result in an assessment.

Sincerely,



FOR, Ron Fellows
Area Manager

Enclosure

cc:
NMOCD

RECEIVED

SEP 08 1986

OIL CON. DIV.
DIST. 3

ABANDONED LOCATION