

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**

Form C-141  
Revised August 8, 2011

**By Jamie at 7:59 am, Sep 21, 2015**

accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company Matador Production Company	Contact Catherine Green
Address 500 N Main St Ste One	Telephone No. 575-623-6601
Facility Name Chevron 12 Fed # 5	Facility Type Oil Well

Surface Owner	Mineral Owner	API No. 30-025-30682
---------------	---------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	12	18S	32E	1650	FNL	1650	FEL	Lea

Latitude 32.7646065 N Longitude -103.7166214 NAD83 \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release Oil	Volume of Release 35BBLs	Volume Recovered 25 BBLs
Source of Release Coupling on a pump failed.	Date and Hour of Occurrence Between 9/15/15 and 9/16/15	Date and Hour of Discovery Sept. 16, 2015 10:00 am
Was Immediate Notice Given? Required <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not	If YES, To Whom? Larry Brigrance, Production Foreman, Matador Resources	
By Whom? Ismael Lopez	Date and Hour Sept. 16, 2015 10:00am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Coupling on a pump failed. Fluid contained in dike. Hauler recovered 25 bbls of fluid.

Describe Area Affected and Cleanup Action Taken.\*

Inside dike. Hauler recovered 25 bbls of fluid. Diamondback Disposal will be on location to collect soil samples, and complete reclamation work. Lab reports and photos will be submitted.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Catherine Green	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Catherine Green	Approved by Environmental Specialist: 	
Title: Regulatory Analyst	Approval Date: 09/21/2015	Expiration Date: 11/21/2015
E-mail Address: cgreen@matadorresources.com	Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guidelines.	Attached <input type="checkbox"/> IRP 3869
Date: Sept. 16, 2015 Phone: 575-623-6601	Geotagged photos of remediation required.	

\* Attach Additional Sheets If Necessary

pJXK1526428657  
nJXK1526428548





CRUDE OIL

16-1  
68084  
43723  
14  
501

90

