

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: ConocoPhillips	Contact: Spencer Cluff
Address: 29 Vacuum Complex Lane	Telephone No. 575-746-7248
Facility Name: EVGSAU 3236-004	Facility Type: Well

Surface Owner: NMOCD	Mineral Owner: NMOCD	API No. 30-025-02979
-----------------------------	-----------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	32	17S	35E	1980	North	1980	West	LEA

Latitude 32.7933311 Longitude 103.4820251 NAD83

NATURE OF RELEASE

Type of Release: Spill	Volume of Release: 19 BBLs	Volume Recovered: 8 BBLs
Source of Release: Flow line	Date and Hour of Occurrence 10/15/2015 12:00 am	Date and Hour of Discovery 10/15/2015 2:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jamie Keyes	
By Whom? Spencer Cluff	Date and Hour: 10/16/2015 9:20 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

On Oct. 15, 2015 at 1400 hrs MDT a flow line leak occurred at the EVGSAU 3236-004, which released 8 BPW and 10 BO with 4 BPW and 4 BO recovered. Spill area is approximately 75'x75' with a depth of 2" in pasture area and will be remediated according to NMOCD and COPC guidelines.

Describe Area Affected and Cleanup Action Taken.*

Immediate action by the MSO was to shut down the well and isolate the flowline. A work order has been submitted to repair the line. The affected area will be remediated according to NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Spencer A. Cluff</i>	Approved by Environmental Specialist: <i>Jamie Keyes</i>	
Printed Name: Spencer A. Cluff	Approval Date: 10/16/2015	Expiration Date: 12/16/2015
Title: LEAD HSE	Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guidelines. Geotagged photos of remediation required.	
E-mail Address: spencer.a.cluff@conocophillips.com	Attached <input type="checkbox"/> 1RP 3923	
Date: 10/16/2015	Phone: 575-746-7248	

* Attach Additional Sheets If Necessary

pJXK1528944902

nJXK1528944722