

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 3:32 pm, Nov 09, 2015

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report

☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077	
Facility Name: Eata Fajita CTB #3	Facility Type: Battery	
Surface Owner: State	Mineral Owner:	API No.

LOCATION OF RELEASE

Unit Letter O	Section 8	Township 24S	Range 33E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude 32.226146 Longitude -103.590631

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 36 bbls Oil	Volume Recovered: 35 bbls Oil
Source of Release: Tank Overflow	Date and Hour of Occurrence: 9/26/2015 5:00 am	Date and Hour of Discovery: 9/26/2015 5:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones – NMOCD	
By Whom? Lupe Carrasco	Date and Hour: Sun 9/27/2015 9:21 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

APPROVED

By JKeyes at 3:32 pm, Nov 09, 2015



Describe Cause of Problem and Remedial Action Taken.*

This release was caused when the Lease Op forgot to remove the equalizer seal and left the valve closed. Vacuum trucks were dispatched to recover all the standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within the lined facility. The facility was cleaned and put back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 		
Title: Senior Environmental Coordinator	Approval Date: 11/09/2015	Expiration Date: ///	
E-mail Address: atrujillo@concho.com	Conditions of Approval: ///		Attached <input type="checkbox"/> IRP 3965
Date: October 10, 2015 Phone: 575-748-6940			

* Attach Additional Sheets If Necessary