



Sign marking location 11-13-15



Impacted area facing west



Impacted area facing northwest



Impacted area facing northwest



Impacted area west side of tanks



Impacted area facing north

**Silver Spike Energy  
Knowles SWD #002  
API 30-025-07287**



Excavated area facing west



Excavated area facing northwest



Excavated area South of battery



Excavated area northwest



Excavated area west side of tanks



Excavated and lined west side of tanks

**Silver Spike Energy  
Knowles SWD #002  
API 30-025-07287**



Lined Excavation facing north



Lined area facing south



Lined west side of tanks with layered top soil



Lined north side layered topsoil



East Background SP



© 2015 Google

South Background SP

Google earth

Hi Kellie,  
The field data on the background samples that you requested is as follows, and I have attached the map indicating the locations of the sample point positions.  
South background Cl <124 mg/kg  
East Background Cl <124 mg/kg  
Non detect on the TPH or BTEX  
I just spoke to Cardinal Labs and they will have the confirmation lab report before the 23rd.  
I have also attached the photo pages for your review of the site progres.  
I hope you get will soon.

Thank You

Rebecca Pons

Safety & Environmental Solutions, Inc.  
703 East Clinton Street  
Hobbs, NM 88240  
Office: (575) 397-0510

Received December 21, 2015