

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077	
Facility Name: Gunner 16 State SWD #1	Facility Type: SWD	
Surface Owner: State	Mineral Owner: State	API No. 30-025-40890

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	16	26S	34E	330'	North	330'	West	Lea

Latitude 32.0497322 Longitude -103.4822998

### NATURE OF RELEASE

Type of Release: Oil & Rain Water	Volume of Release: 0.25 bbls oil; 35 bbls rain water	Volume Recovered: 0 bbls oil; 0 bbls rain water
Source of Release: Illegal Dump	Date and Hour of Occurrence: 9/25/2015 10:00 am	Date and Hour of Discovery: 9/25/2015 10:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones - NMOCD	
By Whom? Amanda Trujillo Davis	Date and Hour: Fri 9/25/2015 4:58 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* <b>APPROVED</b> <b>By Kellie Jones at 2:42 pm, Jan 06, 2016</b>	<b>REVIEWED</b> <b>By Kellie Jones at 2:42 pm, Jan 06, 2016</b>	



#### Describe Cause of Problem and Remedial Action Taken.\*

This release was caused by water hauler with Maverick Coating Services. The driver was tasked with removing standing water from a recent rain from containments and disposing at the SWD. The driver chose not to wait and discharged the contents in his truck in the pasture next to the SWD. Witnesses reported the incident to the security department.

#### Describe Area Affected and Cleanup Action Taken.\*

The release impacted the pasture adjacent to the pad. Soil samples were taken from the impacted area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo Davis	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 01/06/2016	Expiration Date: //
E-mail Address: <a href="mailto:atrujillo@concho.com">atrujillo@concho.com</a>	Conditions of Approval: //	Attached <input type="checkbox"/> 1RP-4076
Date: October 9, 2015 Phone: 575-748-6940		

\* Attach Additional Sheets If Necessary

nKJ1600653087  
pKJ1600653516