

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

RECEIVED

Submit 1 Copy to appropriate District Office in NM AC.
By JKeyes at 1:06 pm, Apr 14, 2016

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: BOBWHITE 12 STATE COM #003H	Facility Type: Battery

Surface Owner:	Mineral Owner: State	API No. 30-025-41137
----------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter A	Section 12	Township 21S	Range 33E	Feet from the 160	North/South Line North	Feet from the 496	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	---------------

Latitude 32.5000954 Longitude -103.5190353

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 400 bbls Oil	Volume Recovered: 395 bbls Oil
Source of Release: Circulating line	Date and Hour of Occurrence: 3/30/2016 11:00 am	Date and Hour of Discovery: 3/30/2016 11:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jaime Keyes - NMOCD	
By Whom? Robert Grubbs	Date and Hour: Thu 3/31/2016 6:18 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a corroded nipple on a circulating line that ran to an oil tank. Vacuum trucks were dispatched to recover standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within the lined facility. Concho will have the spill evaluated for any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.		Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator		Approval Date: 04/14/2016	Expiration Date: 06/14/2016
E-mail Address: rgrubbs@concho.com		Conditions of Approval:	
Date: April 13, 2016 Phone: 432-683-7443		Discrete site samples only. Delineate and remediate per NMOCD guidelines.	
		Attached <input type="checkbox"/> 1RP 4247	

* Attach Additional Sheets If Necessary

nJXK1610547062
pJXK1610547136