## REVIEWED

By Kristen Lynch at 1:33 pm, Oct 20, 2016

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Revised August 8, 2011

Form C-141

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

## **Release Notification and Corrective Action**

		<b>OPERA</b>	ГOR		✓ Initia	al Report	$\boxtimes$	Final Report	
Name of Company OGRID Numb	10-00-00 X (C)	Contact							
Yates Petroleum Corporation 25575				H					
Address		Telephone No.							
104 S. 4 <sup>th</sup> Street		575-748-1471							
Facility Name Renegade BPG Federal #1H	1	Facility Type Battery							
Renegate Bro receial #111		Battery							
Surface Owner Mineral Ov	vner				API No.				
Federal Federal					30-025-39768				
LOCATION OF RELEASE									
		South Line	Feet from the		Vest Line	County			
D   18   26S   35E   660	]	North	330		West	Lea			
Latitude 32.04874 Longitude 103.41406									
NATURE OF RELEASE									
			Volume of Release			Volume Recovered			
N/A		N/A			N/A				
Source of Release Date and Hour of Occ N/A Unknown			Hour of Occurrence	e	Date and Hour of Discovery				
Was Immediate Notice Given?		If YES, To Whom?			9/28/2016; AM				
✓ Yes ☐ No ☐ Not Rec	quired								
By Whom?		Date and Hour							
Robert Asher/Yates Petroleum Corporation		9/29/2016; 2:33 PM (Email)							
Was a Watercourse Reached?		If YES, Volume Impacting the Watercourse.							
☐ Yes ☒ No									
If a Watercourse was Impacted, Describe Fully.*									
Describe Cause of Problem and Remedial Action Taken.*									
Lightning struck a fiberglass tank causing a fire. Area fire departments were called and responded. Vacuum truck(s) and roustabout crews were called.									
Describe Area Affected and Cleanup Action Taken.*									
There was not a release of produced water from the fiberglass tank as the fire burnt down to the water level within the effected tank. The damaged tank and any effected equipment have been removed and will be replaced. This battery is also lined and bermed. <b>Depth to Ground Water: 50-99' (approximately</b>									
50', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10. Based on									
no produced water was released from the fire, Yates Petroleum Corporation requests closure.									
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and									
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability									
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health									
or the environment. In addition, NMOCD acceptance of a C-141 r									
federal, state, or local laws and/or regulations.									
$\bigcirc$ $\bigcirc$ $\land$		OIL CONSERVATION DIVISION							
Signature:		1/ n							
o.g.namer		Approved by Environmental Specialist:							
Printed Name: Robert Asher		Tipple to by Environmental Special							
Title: NM Environmental Regulatory Supervisor		Approval Date: 10/20/2016			Expiration Date: N/A				
E-mail Address: boba@yatespetroleum.com		Conditions of Approval: N/A							
					Attached				
Date: October 14, 2016 Phone: 575-748-4217	7	1RP-				1RP 4473			

<sup>\*</sup> Attach Additional Sheets If Necessary