From: Yu, Olivia, EMNRD

To: "Juana Gaytan"; stucker@blm.gov

Cc: Amy Crawford
Subject: RE: CCC OIL & GAS

Date: Tuesday, February 6, 2018 3:54:00 PM

Attachments: 1RP4958.pdf

## Dear Ms. Crawford:

## Notes:

- NMOCD database indicates Federal mineral ownership. BLM can verify.
- Please be advised that photo documentation indicates > 5 bbls release. The volume has been changed to unknown.

## The 1RP for this incident is

4958	2/6/2018	А	CCC Oil & Gas	Vaughn A 15 battery	30-025-09589	24S-36E-15J/O	1/17/2018

Please remember to include this 1RP identifier to all communications. Also, please be advised that a release characterization/delineation workplan as detailed in the attachment must be approved by NMOCD BEFORE any remediation work.

Thanks,

Olivia Yu Environmental Specialist NMOCD, District I Olivia.yu@state.nm.us 575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Juana Gaytan [mailto:qualityjuana@yahoo.com]

Sent: Tuesday, February 6, 2018 2:09 PM

To: Yu, Olivia, EMNRD < Olivia. Yu@state.nm.us>
Cc: Amy Crawford < randyamyandboys@aol.com>

Subject: CCC OIL & GAS

Hi There,

Here is the form that we spoke about this morning, sorry it took so long.

Please let me know what else I need to do.

Thank You,

Hope you are feeling better!

Juana A. Gaytan Quality Transport Inc. Jal, NM 88252 575-395-2273 From: Yu, Olivia, EMNRD

To: <u>"RANDYAMYANDBOYS@AOL.COM"</u>

Subject: RE: reportable release at Vaughn A 15 Battery
Date: Monday, January 29, 2018 3:58:00 PM

## Mr. Crawford:

Please be advised that the initial C-141 is due by the end of the week. If you have concerns or questions regarding corrective actions, please make an in-person meeting with me.

Thanks, Olivia

From: Yu, Olivia, EMNRD

**Sent:** Friday, January 19, 2018 3:13 PM **To:** RANDYAMYANDBOYS@AOL.COM

**Subject:** reportable release at Vaughn A 15 Battery

Dear Mr. Crawford:

A NMOCD inspector observed a reportable release at Vaughn A-15 Battery on Wednesday, January 17, 2017. Another visit today, January 19, indicated that the release has been partially removed. While NMOCD does not preclude the Responsible Operator from any immediate clean-up activities, such was picking up standing fluids, further corrective actions will be necessary.

Per NMAC 19.15.29, NMOCD must be informed verbally within 24 hours of a major release (>25 bbls). Between 5-25 bbls of fluids, NMOCD must receive written notification on an initial C-141 form within 15 days. The C-141 for this release is due by February 3, 2018. Electronic submission is the preferred method.

Thanks,

Olivia Yu Environmental Specialist NMOCD, District I Olivia.yu@state.nm.us 575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

 From:
 Robinson, Gary, EMNRD

 To:
 Yu, Olivia, EMNRD

 Subject:
 CCC Oil & Gas

**Date:** Friday, January 19, 2018 2:23:15 PM

Olivia, I put some pictures on the L drive of a leak I found 1-17-2017 at the Vaughn A 15 Batt. I went back by the location today and the oil was covered up w/ dirt.

Gary Robinson NMOCD Compliance Officer Hobbs, NM