

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: EOG Resources, Inc.	Contact: Zane Kurtz
Address: 5509 Champions Drive, Midland, TX 79706	Telephone No.: 432-425-2023
Facility Name: Fox 30 State #3 and #4	Facility Type: Lease Road Near Active Well

Surface Owner: State	Mineral Owner: State	API No.: 30-025-41249 (#3)
----------------------	----------------------	----------------------------

LOCATION OF RELEASE

Unit Letter H	Section 30	Township 25S	Range 34E	Feet from the 2140	North/South Line N	Feet from the 715	East/West Line W	County Lea
------------------	---------------	-----------------	--------------	-----------------------	-----------------------	----------------------	---------------------	---------------

Latitude 32.1029 Longitude -103.5027

NATURE OF RELEASE



Type of Release: Produced Water	Volume of Release: 50 BBLs	Volume Recovered: 40 BBLs
Source of Release: Produced water poly line	Date and Hour of Occurrence 11/21/14	Date and Hour of Discovery 1500
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NA	
By Whom? NA	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* NA	APPROVED <i>By Olivia Yu at 11:09 am, Mar 13, 2018</i>
---	--

Describe Cause of Problem and Remedial Action Taken.*
Lease op found leaking 4 inch poly line on lease road near well. About 50 bbls of produced water was spilled and 40 bbls was recovered by vacuum truck. Impacted area was excavated with backhoe and CH2M Hill was onsite to collect soil samples to delineate vertical and horizontal impacts. Soil was stockpiled on poly plastic and was hauled off for proper disposal.

Describe Area Affected and Cleanup Action Taken.*
Between November 25, 2014 and August 1, 2016, several sampling events were performed and the horizontal and vertical extent of petroleum hydrocarbons and chloride had been assessed. A 20 mil liner was placed within the excavation prior to backfilling with clean soil. The area was then re-seeded.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Zane Kurtz	Approved by Environmental Specialist: 	
Title: Sr. Environmental Representative	Approval Date: 3/13/2018	Expiration Date: xx/xx/xxxx
E-mail Address: zane_kurtz@eogresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: May 31, 2017	Phone: 432-425-2023	

* Attach Additional Sheets If Necessary

1RP-3460