

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating, LLC (OGRID# 229137)	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No.: 432-683-7443	
Facility Name: Bobwhite 12 State Com #004H	Facility Type: Well	
Surface Owner: State	Mineral Owner: State	API No.: 30-025-41092

LOCATION OF RELEASE

Unit Letter O	Section 1	Township 24S	Range 33E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude: 32.501671 Longitude: -103.525217 NAD83

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 20bbls Oil & 40bbls PW	Volume Recovered: 5bbls Oil & 10bbls PW
Source of Release: Flowline	Date and Hour of Occurrence: 1/4/2018	Date and Hour of Discovery: 1/4/2018 9:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Olivia Yu-NMOCD Amber Groves-NMSLO	
By Whom? Rebecca Haskell	Date and Hour: 1/4/2018 1:13pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

APPROVED

By Olivia Yu at 3:36 pm, Jul 03, 2018

Describe Cause of Problem and Remedial Action Taken.*

A nipple near a hammer union failed resulting in the release of approximately 20bbls of oil and 40bbls of produced water. The nipple was replaced.



Describe Area Affected and Cleanup Action Taken.*

The release impacted the pasture adjacent to a lease road. A vacuum truck was dispatched to recover freestanding fluids. Concho will have the spill area evaluated for any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

Remediation activities were conducted in accordance with an NMOCD and NMSLO-approved Workplan and/or associated correspondence with respective regulatory representatives. Please reference the Workplan dated March 5, 2017, and Remediation Summary and Closure Report dated June 19, 2018 for additional details regarding remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Rebecca Haskell		
Title: HSE Coordinator	Approval Date: 7/3/2018	Expiration Date: xx/xx/xxxx
E-mail Address: rhaskell@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/12/18	Phone: 432-818-2372	

* Attach Additional Sheets If Necessary

1RP-4921