

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	OXY USA INC	Contact	WADE DITTRICH
Address	PO BOX 4294; HOUSTON, TX 77210	Telephone No.	575-390-2828
Facility Name	Ridge Runner 7 St #1H CTB	Facility Type	CTB
Surface Owner	State	Mineral Owner	
		API No.	30-025-41646

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	7	22S	33E					LEA

Latitude N 32.40353' Longitude W 103.61929° NAD83

NATURE OF RELEASE

Type of Release	PRODUCED WATER	Volume of Release	50 BBLS	Volume Recovered	45 BBLS
Source of Release	Nipple clamps blew out on the water transfer pump meter	Date and Hour of Occurrence	11/01/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	KRISTEN LYNCH-NMOCD		
By Whom?	KATHY @ BBC INTERNATIONAL INC	Date and Hour	11/03/16 @ 4:41 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
<div><b>APPROVED</b> By Olivia Yu at 12:25 pm, Aug 07, 2018</div>					



Describe Cause of Problem and Remedial Action Taken.\*

The nipple clamps blew out on the water transfer pump meter causing a leak in the tank battery of 50 bbls produced water. A vacuum truck recovered 45 bbls of fluids and the meter was returned to service.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 145'x 100' on location inside the battery. Remediation was completed in accordance with a remediation plan approved by NMOCD (Olivia Yu 3-6-17).

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: WADE DITTRICH		Approved by Environmental Specialist: 	
Title: ENVIROMENTAL SPECIALIST		Approval Date: 8/7/2018	Expiration Date: xx/xx/xxxx
E-mail Address: wade_dittrich@oxy.com		Conditions of Approval:	
Date: 8-20-17 Phone: 575-390-2828		NMSLO like approval.	
		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

1RP-4514