

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Marathon Oil Company	Contact Callie Karrigan	
Address 5555 San Felipe St, Houston TX, 77056	Telephone No. 405-202-1028 (cell) 575-297-0956 (office)	
Facility Name Abe Unit #2	Facility Type Gas Well	
Surface Owner State	Mineral Owner State	API No. 30-025-34146

### LOCATION OF RELEASE

Unit Letter H	Section 29	Township 21S	Range 33E	Feet from the 1650	North/South Line North	Feet from the 660	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	---------------

Latitude\_32.4525604\_\_\_\_\_ Longitude\_-103.5881958\_\_\_\_\_ NAD83

### NATURE OF RELEASE

Type of Release spill/fire	Volume of Release unknown	Volume Recovered unknown
Source of Release flare	Date and Hour of Occurrence 7/17/2017	Date and Hour of Discovery 7/20/2017
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Olivia Yu/NMOCD, Shelly Tucker/BLM	
By Whom? Wendy Gram	Date and Hour 7/21/2017	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\* N/A


Describe Cause of Problem and Remedial Action Taken.\*

Impacted area 60' by 150' and 1 to 3 inches depth. Failure in the heater treater caused liquid to build up in the gas sales line, which traveled to the flare, causing a fire. Well is a gas well and does not produce much liquid according to production history.

Describe Area Affected and Cleanup Action Taken.\*

Immediate actions taken at time of incident and remedial action outlined in closure report submitted to NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Callie Karrigan		OIL CONSERVATION DIVISION	
Printed Name: Callie Karrigan		Approved by Environmental Specialist: 	
Title: HES Professional	Approval Date: 9/14/2018	Expiration Date: xx/xx/xxxx	
E-mail Address: cnkarrigan@marathonoil.com	Conditions of Approval: NMSLO approval		Attached <input type="checkbox"/>
Date: 5/29/2018	Phone: 405-202-1028		

\* Attach Additional Sheets If Necessary

1RP-4776

