

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources **HOBBS OGD**  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

AUG 28 2014

**Release Notification and Corrective Action**

RECEIVED

**OPERATOR**

Initial Report  Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	PROHIBITION FEDERAL UNIT #002	Facility Type	SWD

Surface Owner	Federal	Mineral Owner		Lease No. (API#)	30-025-31716
---------------	---------	---------------	--	------------------	--------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	11	22S	32E					Lea

Latitude 32.40443 Longitude 103.64730

**NATURE OF RELEASE**

Type of Release	Oil and produced water	Volume of Release	10bbls of oil 30bbls of produced water	Volume Recovered	7bbls of oil 25bbls of produced water
Source of Release	Water tank	Date and Hour of Occurrence	09-24-2013	Date and Hour of Discovery	09-24-2013 08:00am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking - NMOCD		
By Whom?	Michelle Mullins	Date and Hour	09-25-2013 07:39		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Plunger on triplex pump broke. Replaced the triplex pump.

Describe Area Affected and Cleanup Action Taken.\*

Initially 10bbls of oil and 30bbls of produced water were released due to a mechanical failure on the triplex pump. Causing the water tank to overflow. We were able to recover 7bbls of oil and 25bbls produced water with a vacuum truck. The spill occurred in a unlined facility. All free fluid has been recovered Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a work plan to the NMOCD BLM for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Grubbs Jr.</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Robert Grubbs Jr.		Approved by District Supervisor: <i>Ernest Spalder</i>	
Title: Senior Environmental Coordinator		Approval Date: 8-28-14	Expiration Date: 10-27-14
E-mail Address: rgrubbs@concho.com		Conditions of Approval: SITE Single Report	Attached <input type="checkbox"/> IRP-3293
Date: 10-03-2013	Phone: 432-661-6601		

\* Attach Additional Sheets If Necessary

*Robert Grubbs Jr. was  
in per NMOCD guide  
Submit final C-141 by  
10-27-14*

*Ognd 229137  
NTO 1424041693  
P701424041809*

AUG 28 2014