

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC [OGRID] 229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: COSMO 8 STATE #004H	Facility Type: Battery

Surface Owner: State	Mineral Owner: State	API No. 30-025-40348
----------------------	----------------------	----------------------

#### LOCATION OF RELEASE

Unit Letter P	Section 08	Township 21S	Range 34E	Feet from the 660'	North/South Line South	Feet from the 660'	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.4879417 Longitude - 103.485527

#### NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 9 bbls pw	Volume Recovered: 8.5 bbls pw
Source of Release: Heater Treater	Date and Hour of Occurrence: 9-19-2017 11:00 am	Date and Hour of Discovery: 9-19-2017 11:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

**RECEIVED**

By Olivia Yu at 4:40 pm, Sep 21, 2017



Describe Cause of Problem and Remedial Action Taken.\*

The release occurred when a hole developed in the fire tube of the heater treater. The heater treater has been taken out of service and a new fire tube is being installed.

Describe Area Affected and Cleanup Action Taken.\*

The release remained within the lined facility. Vacuum trucks were dispatched to recover all free fluids. Concho will have the spill area evaluated for any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Dakota Neel		Approved by Environmental Specialist: 	
Title: HSE Coordinator		Approval Date: 9/21/2017	Expiration Date:
E-mail Address: dneel2@concho.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: September 20, 2017 Phone: 575-746-2010		Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.	

\* Attach Additional Sheets If Necessary

nOY1726456366