

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company EOG Y Resources, Inc.	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 <sup>th</sup> Street	Telephone No. 575-748-1471	
Facility Name Resolute BTO Federal Com #2H	Facility Type Battery	

Surface Owner Federal	Mineral Owner Federal	API No. 30-025-41452
--------------------------	--------------------------	-------------------------

**LOCATION OF RELEASE**

Unit Letter G	Section 24	Township 25S	Range 32E	Feet from the 2590	North/South Line North	Feet from the 2200	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.11621 Longitude 103.62697

**NATURE OF RELEASE**

Type of Release Produced Water	Volume of Release 200 B/PW	Volume Recovered 200 B/PW
Source of Release Water transfer pump	Date and Hour of Occurrence 1/22/2017; AM	Date and Hour of Discovery 1/22/2017; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kristen Lynch/NMOCD I	
By Whom? Robert Asher/EOG Y Resources, Inc.	Date and Hour 1/23/2017; AM	<b>REVISED</b> 7:35 am, Mar 23, 2018
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

Water transfer pump failed to start, overflowing the tank and causing the release. Vacuum truck(s) and roustabout crews were called.

Describe Area Affected and Cleanup Action Taken.\*

An approximate area of 120' X 60', all contained within the spray lined containment battery. The well was shut in, the pump was reset to begin pumping water off of tanks, all (100%) of the released produced water was recovered using a vacuum truck. **Depth to Ground Water: >100' (approximately 325', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Based on all produced water recovered and lined containment, EOG Y Resources requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Robert Asher	Approved by Environmental Specialist:	
Title: Environmental Supervisor	Approval Date:	Expiration Date:
E-mail Address: Robert_Asher@eogresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: February 3, 2017	Phone: 575-748-4217	<b>IRP-</b>

\* Attach Additional Sheets If Necessary

nOY1808227092

**From:** Bob Asher  
**To:** [Lynch, Kristen, EMNRD](#); [Yu, Olivia, EMNRD](#); [Oberding, Tomas, EMNRD](#); [stucker@blm.gov](mailto:stucker@blm.gov)  
**Cc:** [Amber Griffin](#); [Chase Settle](#); [Katie Parker](#); [Veronica Alvarado](#)  
**Subject:** Release Notification (Resolute BTO Federal Com #2H)  
**Date:** Monday, January 23, 2017 6:01:01 AM  
**Attachments:** image001.png

---

**EOG Y Resources, Inc. is reporting a release at the following location (1/22/2017, 6:00 AM).**

Resolute BTO Federal Com #2H  
30-025-41452  
Section 24, T25S-R32E  
2590' FNL & 2200' FEL  
Lea County, New Mexico

**Released: Approximately 200 B/PW; Recovered: 200 B/PW.**

Cause of the release was from a water transfer pump that did not start which caused the tank (s) to overflow, releasing produced water. **The release was contained within a lined/metal containment battery.** Vacuum truck(s) and roustabout crews were called, **vacuum trucks recovered all of the released produced water.** A Form C-141 with complete information will be submitted.

Thank you.

**Robert C. "Bob" Asher**  
**Environmental Supervisor**  
**Safety & Environmental Department**  
**EOG Resources, Inc.**  
**Artesia Division Office**  
105 S. 4<sup>th</sup> Street  
Artesia, NM 88210  
575-748-4217 (Office)  
575-365-4021 (Cell)  
**EOG Safety Begins With YOUR Safety**



**From:** Tucker, Shelly  
**To:** [Bob Asher](#)  
**Cc:** [Lynch, Kristen, EMNRD](#); [Yu, Olivia, EMNRD](#); [Amber Griffin](#); [Veronica Alvarado](#)  
**Subject:** Re: Form C-141 Initial/Final Report (Resolute BTO Federal Com #2H, 1/22/2017)  
**Date:** Sunday, February 5, 2017 12:18:55 PM  
**Attachments:** image001.png

---

BLM accepts your initial/final C-141 for this release. Please ensure you pressure wash your facility to cleanup residue.

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

*Shelly J Tucker*

Environmental Protection Specialist  
O&G Spill/Release Coordinator

Bureau of Land Management  
620 E. Greene St  
Carlsbad, NM 88220

575.234.5905 - Direct  
575.361.0084 - Cellular  
575.234.6235 - Emergency Spill Number

[stucker@blm.gov](mailto:stucker@blm.gov)

The **BLM acceptance/approval does not** relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

**Confidentiality Warning:** This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

On Fri, Feb 3, 2017 at 7:50 PM, Bob Asher <[Bob\\_Asher@eogresources.com](mailto:Bob_Asher@eogresources.com)> wrote:

The Depth to Ground Water is based off of information on the 'ChevronTexaco Trend Map'. The NMOSE website was down and no information was available.

Thank you.

**Robert C. “Bob” Asher**

**Environmental Supervisor**

**Safety & Environmental Department**

**EOG Resources, Inc.**

**Artesia Division Office**

105 S. 4<sup>th</sup> Street

Artesia, NM 88210

575-748-4217 (Office)

575-365-4021 (Cell)

**EOG Safety Begins With YOUR Safety**

