

# WELL LOGS

K Z

API number:	<b>30-025-40615</b>		
OGRID:		Operator:	<b>APACHE CORP</b>
		Property:	<b>J R PHILLIPS</b> # 12

surface

ULSTR:	<b>B</b>	<b>1</b>	<b>T 20S</b>	<b>R 36E</b>
		<b>570</b>	<b>FNL</b>	<b>2240</b>
			<b>FEL</b>	

BH Loc

ULSTR:	<b>B</b>	<b>1</b>	<b>T 20S</b>	<b>R 36E</b>
		<b>660</b>	<b>FNL</b>	<b>2310</b>
			<b>FEL</b>	

Ground Level:	<b>3581</b>	DF:	<b>3593</b>	<b>3593</b>	<b>3594</b>
Datum:	<b>KB</b>		TD:	<b>7724</b>	

Land: <b>FEE</b>	Completion Date: (1)	<b>11/15/2012</b>
	Date Logs Received:	<b>10/1/2012</b>
	Date C105 Received:	<b>1/9/2013</b>
	Date Logs/C105 Due in: (2)	<b>12/5/2012</b>

Confidential:	<b>NO</b>	Date out:	
---------------	-----------	-----------	--

Confidential period: 90 Days for State & Fee, 1 Year for federal

Date Due In: (1) is equal to Completion Date (1) + 20 days

Logs	Depth interval		
<b>TD LD CN/GR</b>	<b>200</b>	<b>7642</b>	Three Detector Litho-Density
<b>HRLA</b>	<b>4823</b>	<b>7660</b>	High Resolution Laterolog
<b>BHC</b>	<b>4823</b>	<b>7689</b>	Borehole Compensated Sonic
	<b>4823</b>	<b>7642</b>	Mechanical Sidewall Coring Tool
	<b>4823</b>	<b>7614</b>	Hostile Natural Gamma Ray

K Z

## OCD TOPS

Rustler	957	Strawn		
Tansill		Atoka		
Yates	2347	Morrow		
7 rvrs	2600			
	2869	Austin		
	2934	Chester		
Queen	3062	Miss Lime		
Penrose	3170			
Grayburg	3368			
San Andres	3702			
Glorieta	5046			
Paddock	5113			
Blinebry				
Tubb	6330			
Drinkard	6600			
Abo	6947			
Wolfcamp				

FEB 04 2013