## RECEIVED

## **Operator Copy**


JUN 12 2013

Form 3160-5, 408B50CD (March 2012) 408B50CD **UNITED STATES** 

COPA

FORM APPROVED OMB No. 1004-0137

DEPARTMENT OF THE INTERIOR					Expires: October 31, 2014			
BUREAU OF LAND MANAGEMENT					5. Lease Serial No.			
SUNDRY NOTICES AND REPORTS ON WELLS					6. If Indian, Allottee or Tribe Name			
	orm for proposals t Use Form 3160-3 (A			;.				
SUBMIT IN TRIPLICATE – Other instructions on page 2.					7. If Unit of CA/Agreement, Name and/or No.			
. Type of Well								
Oil Well Gas Well Other INJECTION					8. Well Name and No. SOUTH JUSTIS UNIT I #260			
Name of Operator LEGACY RESER	RVES OPERATING LP				9. API Well No. 30-025-12438			
a. Address PO BOX 10848 MIDLAND, TX 79702	3b. Phone No. (include area code) 432-689-5200			10. Field and Pool or Exploratory Area  JUSTIS; BLINEBRY-TUBB-DRINKARD				
Location of Well (Footage, Sec., T.,R.,M., or Survey Description)			11. County or Parish, State					
330' FSL & 330' FWL, UNIT LETTER M, SEC 30, T-25-S, R-38-E					LEA CO., NM			
12. CHEC	K THE APPROPRIATE BO	X(ES) TO INDIC	ATE NATURE	OF NOTIC	E, REPORT OR OTHE	ER DATA		
TYPE OF SUBMISSION	E OF ACT	ION						
Notice of Intent	Acidize	Deepen		Produ	ction (Start/Resume)	Water Shui	ı-Off	
	Alter Casing	Fractur	≿ Treat ,	Recla	mation	Well Integr		
✓ Subsequent Report	Casing Repair	New C	onstruction	Reco	mplete		T & REQUEST	
	Change Plans		d Abandon	Temp	orarily Abandon		NTH TA	
Final Abandonment Notice	Convert to Injection	· Plug B	ick	Wate	Disposal	EXIE	NSION	
Legacy Reserves Operating LF for a period of 6 additional mon We pressure tested the subject Chart attached.  We will file a sundry notice with And, we will initiate field operat Based on this forecasted timing potential BLM inspections and	iths. Presently, the currer well on 4/26/13 to a test in the next 45 days, by Alions within the next 90 days, approximately 90 days submitting required paper	nt approved temporessure of 519#  ugust 15, 2013, v  ys, by September  should be availa  work to your offi	erary abandon spring for 30 mi vith our intenticer 15, 2013, to pole for completice.  O LIKE	nutes and on to re-act perform we	to expire on June 20 the casing tested suc- livate or PXA the subjuty If work approved by y If operations, perform SEE A	D, 2013. cessfully. ject well. your office. ing any		
		PPROVAL E	Y STATE		CONDITIC	INS OF AI	PROVAL	
14. I hereby certify that the foregoing is	true and correct. Name (Print	ed/Typed)				•	•	
KENT WILLIAMS Title SENIOR ENGINE					R			
Signature Latwi	ulm		Date 06/05/20	)13		· 		
	THIS SPACE	FOR FEDE	RAL OR ST	ATE OF	FICE USE DRA	NVFN		
Approved by	Shell	-	Title	67		Date		
Conditions of approval, if any, are attached that the applicant holds legal or equitable	Approval of this notice do title to those right in the subj	es not warrant or co	ertify		JUN = 7	AUIO		



## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
  - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
  - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
  - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
  - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
  - e: Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

- Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

South Justis Unit TR-I #260 Submit Subsequent Report and well bore diagram with all Perforations and CIBP with tops of cement. Well may be approved to be TA/SI for a period of 6 months with successful MIT and subsequent report is submitted. This will be the last and only TA/SI approval. Well must be P&A or injecting/producing after 12/07/2013.