

JUN 25 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-28343
Property Name SOUTH HOBBS (G/SA) UNIT	Well No. 140

Surface Location

UL - Lot L	Section 4	Township 19-S	Range 38-E	Feet from 1485	N/S Line SOUTH	Feet From 1245	E/W Line WEST	County LEA
---------------	--------------	------------------	---------------	-------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status <i>active</i>	SHUT-IN	PRODUCING <i>val</i>	DATE <i>6-17-13</i>
------------------------------	---------	-------------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	<i>cmf</i>	<i>NA</i>	<i>NA</i>	<i>45</i>	<i>55</i>
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Exempt From Survey

A cmf pipe to surface ✓

BE Hubbard

ECG/ocd 6-26-2013

Signature: <i>Mendy Johnson</i>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: <i>mendy_johnson@oxy.com</i>	
Date: <i>6/25/2013</i>	Phone: 806-592-6280
Witness:	

JUL 02 2013