

DEC 13 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron	API Number 30-025-25802
Property Name Central Vacuum Unit	Well No. 121

7. Surface Location

UL - Lot N	Section 6	Township 18N	Range 35E	Feet from 400	N/S Line FS L	Feet from 2380	E/W Line FW L	County LEA
----------------------	---------------------	------------------------	---------------------	-------------------------	-------------------------	--------------------------	-------------------------	----------------------

Well Status

Well Status TA	SHUT-IN	PRODUCING Ing	DATE 10/29/13	TA
--------------------------	---------	-------------------------	-------------------------	-----------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	0	0	0	850	
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	


If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Accepted for Record Only

MSB

Signature: 	OIL CONSERVATION DIVISION
Printed name: Danny Acosta	Entered into RBDMS
Title: ALCR	Re-test
E-mail Address: DNLC@chevron.com	
Date: 10/29/13	Phone: 575-631-9033
Witness:	

JAN 06 2014