

HOBBS OCD

State of New Mexico  
 Energy, Minerals and Natural Resources Department  
 Oil Conservation Division Hobbs District Office

DEC 13 2013

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEVRON USA, INC.	3007530970
Property Name V6WU	48 Well No.

7. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet from	E/W Line	County
P	25	178	34E	815	FSL	800	FEL	LEA

Well Status

A Well Status	SHUT-IN	OIL PRODUCING	DATE 11/14/13
---------------	---------	---------------	------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	0		70	20	
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Accepted for Record Only  
 MJB 1/9/2014

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION
Printed name: Lynda McQueen	Entered into RBDMS
Title: SSFS	Re-test
E-mail Address: lmb@chevron.com	
Date: 12/3/13	Phone: 575-942-3526
Witness:	

JAN 13 2014