

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name <i>✓</i> Chevron Mud Treatment S.P.	API Number 30-025-03788
Property Name <i>✓</i> Lovington San Andreas Unit	Well No. 11

7. Surface Location

UL - Lot <i>✓</i> F	Section 36	Township 16S	Range 36E	Feet from 1980	N/S Line FNL	Feet from 1980	E/W Line FWL	County LEA
------------------------	---------------	-----------------	--------------	-------------------	-----------------	-------------------	-----------------	---------------

Well Status

Well Status <i>✓</i> A	SHUT-IN	PRODUCING <i>✓</i> <i>Trig</i>	DATE 10/14/13
---------------------------	---------	-----------------------------------	------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod-Tubing	(E) Tubing
Pressure	\emptyset		\emptyset 300		1900
Flow Characteristics					
Puff	Y/N	Y/N	Y/ \emptyset	Y/N	
Steady Flow	Y/N	Y/N	\emptyset N	Y/N	
Surges	Y/N	Y/N	Y/ \emptyset	Y/N	
Down to nothing	Y/N	Y/N	\emptyset N	Y/N	
Gas or Oil	Y/N	Y/N	Y/ \emptyset	Y/N	
Water	Y/N	Y/N	Y/ \emptyset	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

good MET
300# pressure blew down to 0#
> Pressure Limit = 1740 Per. IPI - Feb, 1995
> Over pressure limit violation letter 1/2014

Accepted for Record Only
YMSB

Signature: <i>Danny Acosta</i>	OIL CONSERVATION DIVISION
Printed name: Danny Acosta	Entered into RBEMS
Title: ALCR	Re-test
E-mail Address: DNLC@chevron.com	
Date: 10/14/13	Phone: 575-631-9033
Witness:	