

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 24 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEURON					API Number 30-025-24316				
Property Name VACUUM GRAYBURG SAN ANDRES UNIT					Well No. 17				
Surface Location									
UL - Lot 1	Section 2	Township 18S	Range 34E	✓	Feet from 1400	N/S Line FSL	Feet From 10	E/W Line FEL	County LEA
Well Status									
TAD WELL YES ☐ NO ☒		SHUT-IN YES ☒ NO ☐		INJECTOR INJ SWD ☐		PRODUCER OIL ☐ GAS ☐		DATE 5/5/14	

OBSERVED DATA


	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			0	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Well is shut in due to inability to perform Annual MIT last year. Monobore injector.

FOR RECORD ONLY

BZ 9/5/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dane McGovern		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lnnb@chevron.com			
Date: 7/10/14	Phone: 575 942-3526		
Witness:			

SEP 15 2014