

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

NOV 25 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name DXL USA	API Number 30-025-055300000
Property Name East Eumont	Well No. 9

7. Surface Location

UL - Lot 0	Section 33	Township 18S	Range 37E	Feet from 640	N/S Line S	Feet From 1650	E/W Line E	County LEC
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

Well Status	SHUT-IN	PRODUCING Injection (Active)	DATE	Water injection
-------------	---------	--	------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	Ops?			Ops?	
Flow Characteristics					
Puff	Y / D	Y / N	Y / N	Y / N	Y / D
Steady Flow	Y / D	Y / N	Y / N	Y / D	Y / D
Surges	Y / D	Y / N	Y / N	Y / D	Y / D
Down to nothing	Y / D	Y / N	Y / N	Y / D	Y / D
Gas or Oil	Y / D	Y / N	Y / N	Y / D	Y / D
Water	Y / D	Y / N	Y / N	Y / D	Y / D


If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

FOR RECORD ONLY

BS 11/26/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Alex Estrella	Entered into RBDMS
Title: Production Tech	Re-test
E-mail Address: alex.estrella@dxl.com	
Date: 4-15-14	
Phone: 575-390-9889	
Witness:	

DEC 02 2014