

MAR 04 2016

**RECEIVED**

State of New Mexico  
 Energy, Minerals and Natural Resources Department  
 Oil Conservation Division Hobbs District Office

**BRADENHEAD TEST REPORT**

Operator Name <b>Cross Timbers Energy, LLC</b>	API Number <b>3002523567</b>
Property Name <b>North Vacuum ABO Unit</b>	Well No. <b>144</b>

7. Surface Location

UL - Lot <b>P</b>	Section <b>15</b>	Township <b>17S</b>	Range <b>34E</b>	Feet from <b>460</b>	N/S Line <b>FSL</b>	Feet From <b>660</b>	E/W Line <b>FEL</b>	County <b>LEA</b>
----------------------	----------------------	------------------------	---------------------	-------------------------	------------------------	-------------------------	------------------------	----------------------

Well Status

TA'D Well <b>YES</b>	SHUT-IN <b>NO</b>	INJECTOR <b>INJ</b>	PRODUCER <b>OIL</b>	DATE <b>2/25/16</b>
-------------------------	----------------------	------------------------	------------------------	------------------------

**OBSERVED DATA**



	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	$\phi$	2/A	2/A	$\phi$	4250
<b>Flow Characteristics</b>					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 _____
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR. - -
Surges	Y/N	Y/N	Y/N	Y/N	GAS _____
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK	
-------	-------	-------	--------	-------	--

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

*BS 3/9/16*

Signature: 	OIL CONSERVATION DIVISION
Printed name: <b>James Embree</b>	Entered into RBDMS <i>GB</i>
Title: <b>Lease Operator</b>	Re-test
E-mail Address: <b>Jembree@ctfieldsves.com</b>	
Date: <b>2/25/16</b>	Phone: <b>(575) 704-2241</b>
Witness: 	

*FR*