

HOBBS OCD

APR 05 2016

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED	Operator Name Chevron USA Inc.	API Number 30-025-31873
	Property Name UWU - Vac. Clarissa West Unit	Well No. 91

7. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
I	35	17S	34E	1459	S	1048	E	LEA

Well Status

Well Status Active	SHUT-IN X	PRODUCING INJ	DATE 3-23-16
------------------------------	---------------------	-------------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csgng	(E)Tubing
Pressure	0	N/A	N/A	500	0
Flow Characteristics					
Puff	Y / 0	Y / N	Y / N	Y / 0	
Steady Flow	Y / 0	Y / N	Y / N	0 / N	
Surges	Y / 0	Y / N	Y / N	Y / 0	
Down to nothing	0 / N	Y / N	Y / N	0 / N	
Gas or Oil	Y / 0	Y / N	Y / N	0 / N	
Water	Y / 0	Y / N	Y / N	Y / 0	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR —	FRESH —	SALTY —	SULFUR —	BLACK —
----------------	----------------	----------------	-----------------	----------------

Remarks:

INJECTING AT THIS TIME **X** WTR, **—** GAS, **—** CO2

D- Bled to Zero
Built back up to 500 psi in 24hrs. (Oil)
(Failure)

Signature: T. DeLeon	BS 4-8-16 OIL CONSERVATION DIVISION
Printed name: Tanner DeLeon	Entered into RBDMS BS
Title: FSA	Re-test
E-mail Address: T24R @ chevron.com	
Date: 3-23-16	Phone: 575-390-4449
	Witness:

APR 08 2016