

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 15 2016

BRADENHEAD TEST REPORT

RECEIVED

Operator Name APACHE	API Number 30 025 06345
Property Name NEDU	Well No. 117

7. Surface Location

UL - Lot C	Section 2	Township 23	Range 37E	Feet from 921	N/S Line N	Feet From 1650	E/W Line W	County LEA
----------------------	---------------------	-----------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	PRODUCER OIL	GAS	DATE 4-13-16
------------------	-----------	----------------	----	------------------------	-----	-----------------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	1050				
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: David Cummings	OIL CONSERVATION DIVISION
Printed name: DAVID CUMMINGS	Entered into RBDMS
Title: SR PUMPER	Re-test gm
E-mail Address:	
Date: 4-13-16	Phone:
Witness: David Heady	