

HOBBS OCD

AUG 19 2016

RECEIVED

District I
1623 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Lime Rock Resources II-A, L.P.	API Number 30025291920000
Property Name North Vacuum ABO North Unit 9-3	Well No. 003

2. Surface Location

1/4 - Lot 0	Section 2	Township 17S	Range 34E	Feet from 460	N/S Line S	Feet From 1980	E/W Line E	County Lea
----------------	--------------	-----------------	--------------	------------------	---------------	-------------------	---------------	---------------

Well Status

TA'D WELL YES	☒ NO	☒ YES	SHUT-IN NO	☒ INJ	INJECTOR SWD	OIL PRODUCER	GAS	DATE 7-29-16
------------------	-------------------------------------	--------------------------------------	---------------	--------------------------------------	-----------------	-----------------	-----	-----------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Cons	(E) Tubing
Pressure	0	0		0	0
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for water flood if applies.
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Well is shut in as it has a very small
sq. leak. Lime Rock has tried to squeeze with negative
results. we are looking into running a liner.

FAIL -

Signature: <i>Eddie Elliott</i>	OIL CONSERVATION DIVISION
Printed name: Eddie Elliott	Entered into RBDMS
Title: Production Foreman	Re-test
E-mail Address: eelliott@limerockresources.com	
Date: 7-29-16	Phone: 432-413-0429
Witness:	