HOBBS OCD

Submit One Copy To Appropriate District 1 2 1 2017 State of New Mexico District 1 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240 ENERCE NED District II 811 S. First St., Artesia, NM 88210 ECENCED 000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Francis Dr. 0istrict IV Santa Fe, NM 87505	Form C-103 Revised November 3, 2011 WELL API NO. 30-025-05125 5. Indicate Type of Lease STATE FEE \checkmark /
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name Buckley 'B'
1. Type of Well: XOil Well Gas Well Other	8. Well Number 2
2. Name of Operator Resolute Natural Resources Co., LLC	9. OGRID Number 295770
3. Address of Operator 1700 Lincoln St., Suite 2800, Denver, CO 80203	10. Pool name or Wildcat Denton, Devonian
4. Well Location Unit Letter _ D : _ 990 feet from the ^{north} ine and _ 330 feet from the west ine	
Section 25 Township 14S Range 37E NMPM 6 County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3812 ' GL	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL OTUED: MULTIPLE COMPL	
	ady for OCD inspection after P&A
 All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the 	
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR</u> <u>UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR</u> <u>PERMANENTLY STAMPED ON THE MARKER'S SURFACE.</u>	
 The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed 	
from lease and well location.	
All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-	
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE Mury Mars TITLE Sr Regulatory	Analyst DATE 2-16-17
SIGNATURE Muy Muss TITLE Sr Regulatory Analyst DATE 2-16-17 TYPE OR PRINT NAME Sherry Glass E-MAIL: Bass@resoluteenergy.com 303-573-4886 For State Use Only	
APPROVED BY: Malchitah TITLE P.E.S.	DATE 02/21/2017