Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

HOBBS OCD AUG 02 2017 6.1f

FORM APPROVED OMB No. 1004-0137 Expires: January 31, 2018

5. Lease Serial No. LC-059152b

7. If Unit of CA/Agreement, Name and/or No. 8. Well Name and No Paddy 24 Federal No. 1 9. API Well No. 30-025-37378 Inde area code) 10. Field and Pool or Exploratory Area Wildcat G-03 S173318N; Yeso 97727 11. Country or Parish, State Lea County, NM ATE NATURE OF NOTICE. REPORT OR OTHER DATA TYPE OF ACTION Production (Start/Resume) Water Shut-Off E Fracturing Reclamation Well Integrity struction Recomplete Other Abandon Temporarily Abandon Water Disposal ding estimated starting date of any proposed work and approximate duration thereof. If ocations and measured and true vertical depths of all pertinent markers and zones. Attach with BLM/BIA. Required subsequent reports must be filed within 30 days following ion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been cluding reclamation, have been completed and the operator has detennined that the site above mentioned well. This well was completed in Jan. 2006 and has cos on average 3.8 BOPD, 107 BWPD & 0 MFCD. In December of 2012, an
8. Well Name and No Paddy 24 Federal No. 1 9. API Well No. 30-025-37378 10. Field and Pool or Exploratory Area Wildcat G-03 S173318N; Yeso 97727 11 Country or Parish, State Lea County, NM ATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF ACTION Well Integrity Well Integrity Struction Recomplete Other Other Other Abandon Water Disposal ding estimated starting date of any proposed work and approximate duration thereof. If protections and measured and true vertical depths of all pertinent markers and zones. Attach with BLM/BIA. Required subsequent reports must be filed within 30 days following into or recompletion in a new interval, a Form 3160-4 must be filed once testing has been cluding reclamation, have been completed and the operator has detennined that the site above mentioned well. This well was completed in Jan. 2006 and has
8. Well Name and No Paddy 24 Federal No. 1 9. API Well No. 30-025-37378 Inde area code 10. Field and Pool or Exploratory Area Wildcat G-03 S173318N; Yeso 97727 Il Country or Parish, State Lea County, NM ATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF ACTION Water Shut-Off Well Integrity
9. API Well No. 30-025-37378 10. Field and Pool or Exploratory Area Wildcat G-03 S173318N; Yeso 97727 11. Country or Parish, State Lea County, NM AFE NATURE OF NOTICE. REPORT OR OTHER DATA TYPE OF ACTION Production (Start/Resume) Water Shut-Off Practuring Reclamation Well Integrity Struction Recomplete Other Abandon Temporarily Abandon Water Disposal ding estimated starting date of any proposed work and approximate duration thereof. If procations and measured and true vertical depths of all pertinent markers and zones. Attach with BLM/BIA. Required subsequent reports must be filed within 30 days following ion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been cluding reclamation, have been completed and the operator has detennined that the site above mentioned well. This well was completed in Jan. 2006 and has
10. Field and Pool or Exploratory Area Wildcat G-03 S173318N; Yeso 97727 11. Country or Parish, State Lea County, NM ATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF ACTION Water Shut-Off Well Integrity
Lea County, NM ATE NATURE OF NOTICE. REPORT OR OTHER DATA TYPE OF ACTION Production (Start/Resume) Water Shut-Off Reclamation Well Integrity Struction Recomplete Other Abandon Temporarily Abandon Water Disposal ding estimated starting date of any proposed work and approximate duration thereof. If pocations and measured and true vertical depths of all pertinent markers and zones. Attack with BLM/BIA. Required subsequent reports must be filed within 30 days following ion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been cluding reclamation, have been completed and the operator has detennined that the site above mentioned well. This well was completed in Jan. 2006 and has
TYPE OF ACTION Production (Start/Resume) Water Shut-Off' Fracturing Reclamation Well Integrity Struction Recomplete Other Abandon Temporarily Abandon Water Disposal ding estimated starting date of any proposed work and approximate duration thereof. If positions and measured and true vertical depths of all pertinent markers and zones. Attack with BLM/BIA Required subsequent reports must be filed within 30 days following ion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been cluding reclamation, have been completed and the operator has detennined that the site above mentioned well. This well was completed in Jan. 2006 and has
Production (Start/Resume) Water Shut-Off Fracturing Reclamation Well Integrity Struction Recomplete Other Abandon Temporarily Abandon Water Disposal ding estimated starting date of any proposed work and approximate duration thereof. If procations and measured and true vertical depths of all pertinent markers and zones. Attack with BLM/BIA. Required subsequent reports must be filed within 30 days following ion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been cluding reclamation, have been completed and the operator has detennined that the site above mentioned well. This well was completed in Jan. 2006 and has
Reclamation Well Integrity struction Recomplete Other Abandon Temporarily Abandon Water Disposal ding estimated starting date of any proposed work and approximate duration thereof. If ocations and measured and true vertical depths of all pertinent markers and zones. Attack with BLM/BIA. Required subsequent reports must be filed within 30 days following ion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been cluding reclamation, have been completed and the operator has detennined that the site above mentioned well. This well was completed in Jan. 2006 and has
Abandon Water Disposal ding estimated starting date of any proposed work and approximate duration thereof. If ocations and measured and true vertical depths of all pertinent markers and zones. Attache with BLM/BIA. Required subsequent reports must be filed within 30 days following ion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been cluding reclamation, have been completed and the operator has detennined that the site above mentioned well. This well was completed in Jan. 2006 and has
Water Disposal ding estimated starting date of any proposed work and approximate duration thereof. If coations and measured and true vertical depths of all pertinent markers and zones. Attached the BLM/BIA. Required subsequent reports must be filed within 30 days following ion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been cluding reclamation, have been completed and the operator has detennined that the site above mentioned well. This well was completed in Jan. 2006 and has
ding estimated starting date of any proposed work and approximate duration thereof. If ocations and measured and true vertical depths of all pertinent markers and zones. Attack ith BLM/BIA. Required subsequent reports must be filed within 30 days following ion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been cluding reclamation, have been completed and the operator has detennined that the site above mentioned well. This well was completed in Jan. 2006 and has
ring, but was unsuccessful. Based on our current operating costs this well has ompliance and keep the wellbore open for future field development. B. a CIT was performed. This test was witnessed by Steven with the BLM. B. chart. C. 27/2018 with attached written
Engineer ACCEPTED END DECORD
06/28/2017
AL OR STATE OFICE USE
t

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

MUSICO 8/8/2017

RBDMS-CHART-V

CML EXPLORATION, LLC P.O. BOX 890 SNYDER, TX 79550 325-573-1938

CML EXPLORATION, LLC FILE

PADDY 24 FEDERAL NO. 1


Workover Report

- 06/26/17 MIRUPU. Pulled out of the hole with rods & pump. Laid down rods & pump. Hot water tubing with 40 bbls of produced water. NDWH & released TAC. Pulled out of the hole with tubing. Shut well in for the night.
- 06/27/17 Rigged up wireline truck, set CIBP @5800' & bale dumped 35' of cement on top of plug. Top of cement plug @±5765'. Ran in the hole with 178 jts of 2-7/8" tubing & 2-3/8" seat nipple to 5700'. NDBOP, flanged up wellhead. Rigged up pump truck & circulated casing with 200 bbls of packer fluid. Pressure tested casing to 550 psi & rigged down. CIT witnessed by Steven with Bureau of Land Management. RDMOPU.

TUBING DETAIL

178 – jts of 2-7/8" J55 tubing 1 – 2-3/8" seat nipple w/x-over @5700'

WELL IS TEMPORARILY ABANDONED



GANDY COMP MICK S CANT 610

CML Exploration, LLC Paddy - 01, API 3002537378 T17S-R32E, Sec 24, 660FNL & 400FEL

07/20/2017 TA status accepted for record (with an attached written order) for the period of 06/27/2016 until 06/27/2018. pswartz

Compliant well status beyond 06/27/2018 requires:

- 1) a notice of intent procedure to return the wellbore to "beneficial use".
- 2) a notice of intent procedure to abandon the well.
- 3) a subsequent sundry describing installed equipment that will display continuous open to the air packer fluid level above the casing vent.
 - Notify BLM's authorized officer ("Paul R. Swartz" <<u>pswartz@blm.gov></u>, cell phone 575-200-7902) to arrange for approval of the annular monitoring system.
 - Loss of more than the surface packer fluid supply volume within a month requires BLM notification. Gain of annular fluid pressure requires BLM notification within 24 hours.
 - ➤ June of each year submit a Form 3160-5 subsequent sundry report noting any required maintenance of the packer fluid level with justification for continued TA acceptance by BLM.
 - > The BLM idle well (inactive no beneficial use) time limit generally is 5 years.

Federal Oil & Gas leases are held by well production or actively drilling for production during the end of the primary term of the lease. A TA status will not hold the lease.

- 1) If you do not comply as noted, you shall be issued an Incident of Noncompliance (INC) in accordance with 43 CFR 3163.1(a). Failure to comply with the INC may result in assessments as outline in 43 CFR 3163.1, and may also incur civil penalties (43CFR 3163.2). All self-certified corrections must be postmark no later than the next business day after the prescribed time frame for correction.
- 2) Section 109(d)(1) of the Federal Oil and Gas Royalty Management Act of 1982, as implemented by the applicable provisions of the operating regulations at Title 43 CFR 3163.2(f)(1), provides that any person who "knowingly or willfully" prepares, maintains, or submits false, inaccurate, or misleading reports, notices, affidavits, records, data, or other written information required by this part shall be liable for civil penalty of up to \$25,000 per violation for each day such violation continues, not to exceed a maximum of 20 days.
- 3) A person contesting a decision shall request a State Director review of the Written Order. This request must be filed within 20 working days of receipt of the Notice with the appropriate State Director (see 43 CFR 3165.3). The State Director review decision may be appealed to the Interior Board of Land Appeals, 801 North Quincy Street, Suite 300, Arlington, VA 22203 (see 43 CFR 3165.4). Contact the above listed Bureau of Land Management office for further information.

Legal Description: API# 30-025-37278 400' FEL, 660' FNL, Sec 24, T-17-S,R-32-E Survey Lea County New Mexico Spudded: 10/26/2005 446' 171/2" hole TD: 12/1/2005 13 3/8" 48# J55 Completed: 1/21/2006 set @ 446' Stimulation: (6050-53) 500 gals 15% HCL 500 sx cement 12/28/05 CIBP @ 6000' w/ 20' cement 12/31/05 (5854 - 68') 1500gal15%HCL 12/4/08 - 3000 gals of 20% HCL + 100 balls 3/22/12 - 500 gals xylene + 2500 gals of 15% HCL & 100# rock salt 11" hole 12/19/12 Frac 52K gals 15# gel & 62K lbs of 8 5/8" 32# J-55 16/30 sand set @ 4813' 2960sx cemt., TOC = surface' 4813" 5 1/2" TOC @1700' (CBL) PRESSURE DATA NONE **Production Tbg** 178 jts 2 7/8" tubing 1-2 3/8" seat nipple w/ x-over @ 5700' Top of Cement @ 5765' TA PLUG set @ 5800' **Paddock Perfs** 5854-68' (4 spf) 56 holes 51/2" CIBP @ 6000' w/ 20' cement 6050-53' (4 spf) 5 1/2"17#- J-55 @ 6195'

Cmt'd w/ 500 sks

PBTD:

TD:

5980'

6200'