

HOBBS OCD

OCT 02 2017

RECEIVED

BRADENHEAD TEST REPORT

State of New Mexico

Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

Operator Name DAKOTA Resources		API Number 30-025-23985	
Property Name WALLEN Fed.		Well No. #2	

Surface Location									
UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County	
C	20	20s	34E	990	N	1650	W	LEA	

Well Status									
TA'D WELL	SHUT-IN	INJ	INJECTOR	OIL	GAS	DATE			
YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		SWD <input checked="" type="checkbox"/>			9-26-17			

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csmg	(E)Tubing
Pressure	0	N/A	N/A	0	550
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 <input type="checkbox"/>
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR <input checked="" type="checkbox"/>
Surges	Y/N	Y/N	Y/N	Y/N	GAS <input type="checkbox"/>
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.
Pump down - low water

Signature: Dub Rackley	OIL CONSERVATION DIVISION
Printed name: Dub Rackley	Entered into RBDMS
Title: foreman	Re-test [Signature]
E-mail Address:	
Date: 9-26-17	
Phone:	
Witness: Larry Robinson	

575-399-3220