

Submit 1 Copy To Appropriate District Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

OCD-HOBBS

Form C-103  
Revised July 18, 2013

WELL API NO.  
30-025-01635 ✓

5. Indicate Type of Lease

STATE ☐ FEE ☐

6. State Oil & Gas Lease No.

NMLC-063645 NM116168

7. Lease Name or Unit Agreement Name  
EK Queen Unit

NM70937x

8. Well Number 026 ✓

9. OGRID Number  
20497

10. Pool name or Wildcat  
EK - Yates - Seven Rivers - Queen

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other

2. Name of Operator  
Seely Oil Company ✓

3. Address of Operator  
815 W. 10<sup>th</sup> Street, Fort Worth, TX 76102

4. Well Location ✓

Unit Letter K: 2310 feet from the South line and 2310 feet from the West line

Section 24 Township 18 S Range 33E NMPM Lea County, NM

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐  
CLOSED-LOOP SYSTEM ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐  
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Well failed a MIT.

7/13/17 MI & RU CU. TOH w/ pkr & tbg. TIH w/ new plastic lined AD-I pkr & 138 jts 2 3/8" Salta lined tbg.  
Set pkr @ 4278' RKB

7/14/17 Tested to 380 psi (chart enclosed).

Seely Oil Company respectfully requests permission to resume water injection.

ACCEPTED FOR RECORD

BUREAU OF LAND MANAGEMENT  
CARLSBAD FIELD OFFICE

PRBwarty 09/28/2017

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David L. Henderson TITLE President DATE 7/20/17

Type or print name: David L. Henderson E-mail address: dhenderson@seelyoil.com PHONE: 817-332-1377

For State Use Only

APPROVED BY: Maureen Brown TITLE AO/II DATE 10/30/2017  
Conditions of Approval (if any):

RBDMS - CHART - ✓



