

HOBBS OCD

FEB 06 2013

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Cherrow		API Number 30-025-35974	
Property Name W. TEAS YATES		Well No. 443	

Surface Location

UL - Lot I	Section 4	Township 20S	Range 33E	Feet from 1855	N/S Line S	Feet From 660	E/W Line E	County LEA
----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

YES	TA'D WELL NO	YES	SHUT-IN NO	INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE 2-6-18
-----	------------------------	------------	----------------------	------------	----------	-----	-----	----------	-----	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	0
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Pump Down - Line repairs

Signature: Brandon Baty		OIL CONSERVATION DIVISION	
Printed name: Brandon Baty		Entered into RBDMS	
Title:		Re-test JK	
E-mail Address:			
Date:	Phone:		
Witness: Greg Robinson			
575-399-3220			

INSTRUCTIONS ON BACK OF THIS FORM