

FEB 06 2013

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Cherron		API Number 30-025-36079 ✓
Property Name W. Tens Yates		Well No. 945 ✓

Surface Location									
UL - Lot H	Section 9	Township 20s	Range 33E		Feet from 2612	N/S Line N	Feet From 330	E/W Line E	County LEA

Well Status									
YES	TA'D WELL NO	YES	SHUT-IN NO	INJ	INJECTOR NO	SWD	OIL	PRODUCER GAS	DATE 2-6-18

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ✓
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Pump Down - line repairs

Signature: Braxton Galt		OIL CONSERVATION DIVISION	
Printed name: Braxton Galt		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date:	Phone:		
Witness: Gray Robinson			

575-399-3220

INSTRUCTIONS ON BACK OF THIS FORM