

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office
BRADENHEAD TEST REPORT

HOBBS OGD
APR 04 2018
RECEIVED

Operator Name

API Number

	3002527088
--	------------

Well Name

Well No

Santa Fe	130
----------	-----

BEE

Surface Location

UL - Lot SEC Tnsp Range Feet From N/S Line Feet From E/W Line County

P	4	18S	35E	330	S	330	E	LEA
---	---	-----	-----	-----	---	-----	---	-----

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	OIL	PRODUCER GAS	DATE 3-7-18
------------------	----	----------------	----	-----------------	-----	-----	-----------------	----------------

OBSERVED DATA

	(A)Surface	(B)Interm (1)	(C)Interm (2)	(D) Prod Csg	(E)Tubing
Pressure	⊕	⊕	NA	41	50
Flow Characteristics					CO2
Puff	Y / N	Y / N	Y / N	Y / N	WTR
Steady Flow	Y / N	Y / N	Y / N	Y / N	GAS
Surges	Y / N	Y / N	Y / N	Y / N	
Down to Nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks- Please state for each string (A,B,C,D) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Bradley Boroughs</i>	OIL CONSERVATION DIVISION
Print name: <i>Bradley Boroughs</i>	Entered in RBDMS
Title:	Re-test
E-mail Address:	
Date: 3-7-18	Phone: 575-631-5833
Witness:	