Submit One Copy To Appropriate District State of New Mex	cico Form C-103
Office District I Energy, Minerals and Natura	al Resources Revised November 3, 2011
District II 811 S. First St., Artesia, NM 88210  District III  District III  1220 South St. France	30-025-35584
811 S. First St., Artesia, NM 88210  District III  1220 South St. France	5. Indicate Type of Lease  STATE TO FEE
1000 Rio Brazos Rd., Aztec, NM 87410  District IV  Santa Fe, NM	
1220 S. St. Francis Dr., Santa Fe, NM 87505	APR
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUC	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR PROPOSALS.)	
Type of Well:      Oil Well      Gas Well      Other      Name of Operator	8. Well Number #5  9. OGRID Number
Cimarex Energy Co. of Colorado	162683
3. Address of Operator 600 N. Marienfeld, Suite 600, Midland TX 79705	10. Pool name or Wildcat Monument; Tubb
4. Well Location  Unit Letter H: 2310 feet from the N line and 330 feet from the W line	
Section 4 Township 20S Range 37E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3555	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
	REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. P AND A
	CASING/CEMENT JOB
OTHER:   Location is ready for OCD inspection after P&A	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.  Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)  All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE Amithy Crawford TITLE Re	gulatory Analyst DATE 4/10/2018
TYPE OR PRINT NAME Amithy Crawford E-MAIL:	acrawford@cimarex.com PHONE: 432-620-1909  DATE 04/24/2018
For State Use Only	201-2/2018
APPROVED BY: Washington TITLE	,±,5, DATE 04/24/2018