Submit 3 Copies To Appropriate District	State of New Me		Form C-103	
Office District I	Energy, Minerals and Natu	ral Resources	October 25, 2007	
1625 N. French Dr., Hobbs, NM 87240			WELL API NO.	l
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION		30-041-20454	
District III	1220 South St. Fra		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 8	7505	STATE FEE XX	
1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas Lease No. 023845	
SUNDRY NOTICE (DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	ES AND REPORTS ON WEL SALS TO DRILL OR TO DEEPEN O ATION FOR PERMIT" (FORM C-10	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name: Lambirth	
		- 40	0: 7: 5:: 110:::001	
	Gas Well Other	AUG 01201	9 OGRID Number 162928 10. Pool name or Wildcat	
Name of Operator Energen Resources Corporat:	ion	-11/5	162928	ĺ
3. Address of Operator	[01]	BECEIVE	10. Pool name or Wildcat	
3510 N. "A" St. Bldgs. A &	R Midland TY 79705	N-	South Peterson; Penn Associated	ĺ
4. Well Location	B. Filatana. 1x 73703		oodaa oo o	
	1980 feet from the North	<u>line and 1980</u>	_ feet from the <u>East_line</u>	
Section 31 Tow		e 33E NMPM	County Roosevelt	
	11. Elevation (Show whether GR: 4	DR, RKB, RT, GR, etc 4393 GR	:.)	
12. Check Appropriate Box to	Indicate Nature of Notice,	Report, or Other I	Data Data	
NOTICE OF INTE	NTION TO:	SUB	SEQUENT REPORT OF:	ļ
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	☐ ALTERING CASING ☐	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI	NG OPNS. P AND A	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT JO		
FOLE ON ALTER CASING	MOLTIPLE CONTRACTOR	CASIIVO/OLIMEIVI O		
OTHER:			dy for OCD inspection after P&A	_
	-		rator's pit permit and closure plan.	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.				
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
The location has been leveled as			been cleared of all junk, trash, flow lines and	
other production equipment.				
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with				
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
	is have been removed. Portable	e bases have been rem	oved. (Poured onsite concrete bases do not have	е
to be removed.)		an .		
All other environmental concern				
		th 19.15.9.714.B(4)(b)	NMAC. All fluids have been removed from	
non-retrieved flow lines and pipelines				
When all work has been completed, re				
inspection has to be made to a P&A lo				
SIGNATURE Jammy Go	zh Titi	ESr. Prod Sy	perintendent DATE 7-31-18	
		•	<u> Penergen.com</u> HONE <u>432-209-24</u>	83
For State Use Only			a2/// A a	
APPROVED BY Xony July	<u>~</u>	LE Compliance	Office ADATE 8-2-18	
Conditions of Approval, icany:		J	V	