

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

SEP 11 2018

RECEIVED

BRADENHEAD TEST REPORT

Operator Name <i>Robinson</i>	API Number <i>30-025-25897</i> ✓
Property Name <i>Tonto</i>	Well No. <i>7</i> ✓

7. Surface Location

UL - Lot <i>I</i>	Section <i>30</i>	Township <i>19S</i>	Range <i>33E</i>	Feet from <i>1650</i>	N/S Line <i>S</i>	Feet From <i>990</i>	E/W Line <i>E</i>	County <i>LEA</i> ✓
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	------------------------

Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR <i>INJ</i>	SWD	OIL	PRODUCER GAS	DATE <i>9/11/18</i> ✓
--	--	------------------------	-----	-----	-----------------	--------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	<i>N/A</i>	<i>N/A</i>	<i>N/A</i>	<i>0</i>	<i>1200</i>
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / ☒	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / ☒	WTR ☒ ✓
Surges	Y / N	Y / N	Y / N	Y / ☒	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	☒ / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / N	Y / N	Y / N	Y / ☒	
Water	Y / N	Y / N	Y / N	Y / ☒	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature <i>Jason Rohi</i>	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test <i>JR</i>
E-mail Address:	
Date: <i>9/11/18</i>	Phone:
Witness: <i>Day Robinson</i>	