

Submit 1 Copy To Appropriate District Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised July 18, 2013

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505  
HOBBS OGD  
APR 14 2019  
RECEIVED

WELL API NO. 30-025-42947
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name McCLOY SWD
8. Well Number #2
9. OGRID Number 308339
10. Pool name or Wildcat SWD; Devonian (96101)
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3599' GL

SUNDRY NOTICES AND REPORTS ON WELL  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other SWD

2. Name of Operator  
OWL SWD OPERATING, LLC.

3. Address of Operator  
c/o Mike Pippin LLC, 3104 N. Sullivan, Farmington, NM 87401

4. Well Location  
Unit Letter L : 1595 feet from the South line and 369 feet from the West line  
Section 15 Township 24-S Range 32-E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3599' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐  
CLOSED-LOOP SYSTEM ☒  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐  
OTHER: Repair Tbg Leak ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work).  
SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

With communication between the 5-1/2" tbg & 9-5/8" csg, a tbg leak in this SWD well was suspected. On 10/30/18, MIRUSU. On 11/3/18, cut 5-1/2" tbg just above the PKR seal assembly @ 17,142'. Laid down 405 jts 5-1/2" tbg. Mill & fish for PKR seal assembly for 6 days. Recovered seal assembly & laid down. Mill & fish for PKR from 17,140' into open hole @ 17,211' for 7 days. The 7-3/4" liner shoe is at 17,208'. Continued milling & fishing for PKR for 9 days. On 11/25/18, broke thru PKR in open hole @ 17,451'. Milled, reamed, & CO open hole for 6 days. TOH w/3-1/2" drill pipe & BHA. Released rig on 12/3/18.

Operations suspended until 5-1/2" SWD tbg becomes available. The new 5-1/2" SWD tbg & PKR will then be run & set, an MIT test scheduled & conducted, & SWD operations resumed.

Spud Date: 5/11/17

Drilling Rig Release Date: 10/13/17

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mike Pippin TITLE Petroleum Engineer DATE 1/7/19  
Type or print name Mike Pippin E-mail address: mike@pippinllc.com PHONE: 505-327-4573  
**For State Use Only**

APPROVED BY: [Signature] TITLE Petroleum Engineer DATE 01/18/19  
Conditions of Approval (if any):